



INSTRUCTIONS

INSTANT TETHER SYSTEM™

CODE

See individual product for SKU.

MAX LOAD

↳ 3KG / 6.6LBS

NLG ID

Scan the orange tags on compatible NLG products to access detailed product info, certification and installation videos.

TIP

Leave the label free so that it can be easily inspected.

01



Select the correct D Ring Tether for your tool.

02



Cut a length of Tether Tape™ long enough to wrap around the tool at least 6-8 times. Remove the plastic backing strip.

03



Check the tool is clean and locate the D Ring Tether, ensuring that the label is facing up, leaving the webbing catch exposed.

04



Wrap the Tether Tape™ around the D Ring Tether, ensuring that the Tether Tape™ is firmly stretched during application. When stretched correctly the edges of the tape distort and become wavy.

05



Test the tether point before putting the tool into use by pulling down on catch.