



INSTRUCTIONS

TAPE MEASURE TETHER

CODE

↳101414

MAX LOAD

↳1KG / 2.2LBS

NLG ID

Scan the orange tags on compatible NLG products to access detailed product info, certification and installation videos.

01



Open the Tape Measure Tether and release the velcro adjustment system.

02



Place the tape measure inside with belt clip to the back and tighten the side adjustment system.

03



Pull the upper flap over the tape measure firmly and fasten. Repeat with the lower flap to close.

04

Holding the tape measure, test the tether point before putting it into use.